



Main

| | |
|---------------------------------------|--|
| Accessory / separate part destination | CMD prefabricated plug-in busbar trunking |
| Accessory / separate part categor | Busbar accessories |
| Accessory / separate part type | Auxiliary contact |
| Contact application | Early breaking of the control circuit and On/Off signalling Ensuring off-load disconnection |

Complementary

| | |
|------------------------------|-----------------------|
| Auxiliary contacts operation | Early-break |
| Net Weight | 0.09 lb(US) (0.04 kg) |

Ordering and shipping details

| | |
|-------------------|---------------|
| Category | US1000T22449 |
| Discount Schedule | 000T |
| GTIN | 3389110315905 |
| Returnability | Yes |
| Country of origin | US |

Packing Units

| | |
|------------------------------|------------------------|
| Unit Type of Package 1 | PCE |
| Number of Units in Package 1 | 1 |
| Package 1 Height | 2.64 in (6.7 cm) |
| Package 1 Width | 1.81 in (4.6 cm) |
| Package 1 Length | 2.24 in (5.7 cm) |
| Package 1 Weight | 1.34 oz (38.0 g) |
| Unit Type of Package 2 | S01 |
| Number of Units in Package 2 | 32 |
| Package 2 Height | 5.91 in (15.0 cm) |
| Package 2 Width | 5.91 in (15.0 cm) |
| Package 2 Length | 15.75 in (40.0 cm) |
| Package 2 Weight | 3.09 lb(US) (1.402 kg) |

Offer Sustainability

| | |
|--|---|
| California proposition 65 | WARNING: This product can expose you to chemicals including: Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov |
| For all Reach Rohs enquiries contact us at | sustainability@tesensors.com |

Contractual warranty

| | |
|----------|-----------|
| Warranty | 18 months |
|----------|-----------|